Incorporation by Reference

(e) Except as provided by paragraph (a)(2)(ii) of this AD, the actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD11-24A155, dated June 1, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington,

(f) This amendment becomes effective on December 27, 1999.

Issued in Renton, Washington, on November 10, 1999.

D.L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 99-30055 Filed 11-18-99: 8:45 am] BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-AAL-21]

Establishment of Class E Airspace; St. Michael, AK

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule, correction.

SUMMARY: This action corrects the error in the geographic description of a final rule that was published in the Federal Register on October 5, 1999 (64 FR 53889), Airspace Docket 99-AAL-10. **EFFECTIVE DATE:** 0901 UTC, December 30, 1999.

FOR FURTHER INFORMATION CONTACT:

Robert Durand, Operations Branch, AAL-531, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587; telephone number (907) 271-5898; fax: (907) 271–2850; email:

Bob.Durand@faa.gov. Internet address: http://www.alaska.faa.gov/at.

SUPPLEMENTARY INFORMATION:

History

Federal Register Document 99-25850, Airspace Docket 99-AAL-10, published on October 5, 1999, (64 FR 53889), established the Class E airspace area at

St. Michael, AK. The coordinates for the St. Michael Airport are in error. The latitude for the St. Michael Airport should read "lat. 63° 29' 24" N." This action corrects this error.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the error for the the Class E airspace, St. Michael, AK, as published in the **Federal** Register October 5, 1999, (FR Document 99-25850), is corrected as follows: On page 53890. Column 2, correct the latitude for the St. Michael Airport to the following: lat. 63° 29′ 24″ N.

Issued in Anchorage, AK, on November 5,

Willis C. Nelson,

Manager, Air Traffic Division, Alaskan Region.

[FR Doc. 99-30263 Filed 11-18-99; 8:45 am] BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 29840; Amdt. No. 1961]

Standard Instrument Approach **Procedures: Miscellaneous** Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference-approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination-1. FAA Rules Docket, FAA

Headquarters Building, 800

Independence Avenue, SW., Washington, DC 20591;

- 2. The FAA Regional Office of the region in which affected airport is located; or
- 3. The Flight Inspection Area Office which originated the SIAP.

For Purchase—Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, US Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies